

Model	Load	Gravity Center	Torque	Table Dia.	Table Height	Rotation Speed	Welding Current
	lbs.	in.	lb.-in.	in.	in.	rpm	amps
P1-HT	2,200	8	17600	32	35	1.8	1000
P2-HT	4,400	8	35200	40	40	1	1000
P3-HT	6,600	8	52800	47	47	1	1000
P5-HT	11,000	8	88000	47	51	1	1000
P7.5-HT	16,500	8	132000	55	55	0.7	1000
P10-HT	22,000	8	176000	55	55	0.7	1000
P15-HT	33,000	8	264000	59	59	0.5	1000
P20-HT	44,000	8	352000	59	59	0.5	1000
P25-HT	55,000	12	660000	53	63	0.4	1000
P30-HT	66,000	12	792000	58	78	0.3	1000
P40-HT	88,000	12	1056000	65	78	0.3	1000